


Steps To Use Blackhead Vacuum Cleaner

For Clean And Glowing Face



Wash and cleanse your face and disinfect the vacuum tip.

Steam your face to open up the pores before starting.



Plug the device and place the vacuum tip directly over the blackhead area.

Turn on the vacuum and move the device lightly in continuous circular motions.



Do not use the device on the entire face but focus on the blackhead and surrounding areas.

Repeat the gentle motion for 3-5 minutes.



Once applied over every blackhead, turn off the device.

Apply moisturizer or aloe vera gel on the face for a soothing effect.

