

# TIPS FOR PROPER BATTERY USAGE AND CHARGING A SOLAR ATOMIC WATCH



Keep the watch exposed to bright light as much as and whenever possible.

Never let the battery go dead to avoid the hassle of reconfiguring the watch.



Avoid wearing the watch under your sleeve to ensure continuous charging.

Always use the watch in power-saving mode to limit battery drainage.



When not wearing the watch, always ensure it is facing a light source.

Expose the watch to sunlight for slightly longer durations on cloudy days.



Never leave the watch on the car's dashboard to prevent overheating.

Never leave the watch too close to an incandescent lamp.



Never leave the watch exposed to direct sunlight for longer than recommended.

Always handle the watch with caution after charging to prevent burns.

